

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L2	10	((((measur\$3 or measurement\$1 or test\$3 or determin\$3 or monitor\$3 or indicat\$3) near3 (tack\$5 or stick\$3 or adhesive or adhesion)) or (tack near3 meter\$3) or tackmeter\$3) same (roller or cylinder or wheel) near15 (arm or yoke) near15 (gage or gauge or sens\$3 or detect\$3 or transducer)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/11/21 09:15
L3	181	(73/150A).CCLS.	US-PGPUB; USPAT	OR	OFF	2008/11/21 09:23
L5	34	(73/150A).CCLS.	USOCR	OR	OFF	2008/11/21 09:28
L6	49	(73/54.22).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/11/21 09:29
L7	0	brouwers-leonardus.in.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/11/21 09:31
L8	0	gorter-robertus.in.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/11/21 09:31
L9	0	boonen-antonius.in.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/11/21 09:31
L11	325	nederlandse adj organisatie.as.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/11/21 09:32

S5	1068026	(force or stress or strain or load or pressure or compression) near3 (detect\$3 or cell or sens\$3 or indicat\$3 or gage or gauge or determin\$3 or transducer)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/11/20 14:45
S8	49119	(force or stress or strain or load or pressure or compression) near3 (detect\$3 or cell or sens\$3 or indicat\$3 or gage or gauge or determin\$3 or transducer) near5 (roller or cylinder or wheel)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/11/20 14:52
S10	1695	(measur\$3 or measurement\$1 or test\$3 or determin\$3 or monitor\$3 or indicat\$3) near3 (tack\$5 or stick\$3 or adhesive or adhesion) near15 (roller or cylinder\$1 or wheel)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/11/20 15:00
S11	132	S8 and S10	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/11/20 15:01
S12	1220548	(force or stress or strain or load or pressure or compression) near3 (detect\$3 or cell or sens\$3 or indicat\$3 or gage or gauge or determin\$3 or transducer or measur\$3 or measurement)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/11/20 15:42

S13	55392	(force or stress or strain or load or pressure or compression) near3 (detect\$3 or cell or sens\$3 or indicat\$3 or gage or gauge or determin\$3 or transducer or measur\$3 or measurement) near5 (roller or cylinder or wheel)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/11/20 15:42
S14	192	S13 and S10	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/11/20 15:43
S15	32	((tack near3 meter\$3) or tackmeter\$3) same (roller or cylinder or wheel)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/11/20 15:57

11/21/08 9:38:27 AM

C:\Documents and Settings\TBellamy\My Documents\EAST\workspaces\10551076.wsp